




STRAINERS

193 Nickel-plated Y strainer

LOSS DIAGRAM (With water), with 500 μ m filtration degree

193

	1/4"	3/8"	1/2"	3/4"	1"	1"1/4"	1"1/2"	2"
KV	2,20	3,40	3,80	7,20	11	13	15	28






STRAINERS

LOSS DIAGRAM (With water), with 300 μ m filtration degree

193G

	1/4"	3/8"	1/2"	3/4"	1"	1"1/4"	1"1/2"	2"
KV	2,10	3,10	3,50	6,70	9,30	11,00	13,50	18,50





STRAINERS

LOSS DIAGRAM (With water), with 50 μ m filtration degree

193GAS

	1/4"	3/8"	1/2"	3/4"	1"	1"1/4"	1"1/2"	2"
KV	1,70	2,60	3,20	5,50	6,80	7,30	7,80	9,80

