




VALVOLE A SFERA PER GAS PASSAGGIO TOTALE LONDON

066 Valvola a sfera London, passaggio totale

DIAGRAMMA PERDITE DI CARICO (Con acqua), misure da 1/4" a 2"

| | 1/4" | 3/8" | 1/2" | 3/4" | 1" | 1"1/4" | 1"1/2" | 2" | 2"1/2" | 3" | 4" |
|-----------|------|------|-------|-------|-------|--------|--------|-----|--------|-----|-----|
| KV | 3,45 | 5,00 | 15,65 | 26,26 | 41,44 | 63,69 | 101 | 169 | 376 | 472 | 892 |





VALVOLE A SFERA PER GAS PASSAGGIO TOTALE LONDON

DIAGRAMMA PERDITE DI CARICO (Con acqua), misure da 2"1/2 a 4"

| KV | 1/4" | 3/8" | 1/2" | 3/4" | 1" | 1"1/4" | 1"1/2" | 2" | 2"1/2" | 3" | 4" |
|----|------|------|-------|-------|-------|--------|--------|-----|--------|-----|-----|
| | 3,45 | 5,00 | 15,65 | 26,26 | 41,44 | 63,69 | 101 | 169 | 376 | 472 | 892 |

