




VALVOLE A SFERA PER GAS PASSAGGIO TOTALE LONDON

067 Valvola a sfera London, passaggio totale

DIAGRAMMA PERDITE DI CARICO (Con acqua) misure da 1/4" a 2"

	1/4"	3/8"	1/2"	3/4"	1"	1"1/4"	1"1/2"	2"	2"1/2"	3"	4"
KV	3,45	5,00	15,65	26,26	41,44	63,69	101	169	376	472	892





VALVOLE A SFERA PER GAS PASSAGGIO TOTALE LONDON

DIAGRAMMA PERDITE DI CARICO (Con acqua) misure da 2"1/2 a 4"

KV	1/4"	3/8"	1/2"	3/4"	1"	1"1/4"	1"1/2"	2"	2"1/2"	3"	4"
	3,45	5,00	15,65	26,26	41,44	63,69	101	169	376	472	892

