



VÁLVULAS DE ESFERA PASO TOTAL IDEAL

090 Válvula de esfera Ideal, paso total

DIAGRAMA DE PÉRDIDAS DE CARGA (con agua)

	1/4"	3/8"	1/2"	3/4"	1"	1"1/4"	1"1/2"	2"	2"1/2"	3"	4"
KV	3,45	5,00	15,65	26,26	41,44	63,69	101	169	348	390	725

