



# FULL FLOW BALL VALVES: IDEAL

## 098SB Ideal ball valve with o-ring, full flow for manifolds

### LOSS DIAGRAM (With water)

	1/2"	3/4"	3/4"X1"	1"	1"1/4"
KV	15,65	26,26	26,26	41,44	63,69

